

OUT 54868

P 182134Z
 FM NPIC WASHDC *Multi*
 TO RUCSC/SAC OFFUTT AFB OMAHA NEB
 RUCVAA/4030 STRAT WG OL 19 BARKSDALE AFB LA
 RUCVAA/2D RTS BARKSDALE AFB LA
 RUEAHQ/DIA WASHDC
 RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
 RUEPIA/CIA WASHDC
 RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
 RUWGAA/2AF BARKSDALE AFB LA
 BT

1965 JAN 18 21 57Z

SECRET CITE NPIC 3680.
 15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B 15 WAS USED IN MISSION 3934 FLOWN ON 15 JANUARY
 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD. 19 JAN 1965

B. 9R SIDE: SPOT STATIC DISCHARGES, EDGE FOG, AND OCCASIONAL
 ROLLER CHATTER MARKS ARE PRESENT NEAR THE OUTBOARD EDGE ALONG WITH
 CONTINUOUS ROLLER CHATTER AT THE INBOARD EDGE THROUGHOUT THE MISSION.
 A PLUS DENSITY STREAK 3.3" FROM THE INBOARD EDGE IS PRESENT
 THROUGHOUT. ANOTHER PLUS DENSITY STREAK APPEARS 4.4" FROM THE
 EDGE AND CONTINUES INTERMITTENTLY TO THE END OF THE MISSION.
 SEVERAL INTERMITTENT PARALLEL SCRATCHES SPACED APPROXIMATELY
 0.25" APART ARE LOCATED WITHIN THE 1.5" ADJACENT TO THE INBOARD
 EDGE FROM FRAME 0001 TO 1064. THE MOST PROMINENT OF THESE SCRATCHES
 IS 1.0" FROM THE EDGE. ABRASIONS, SCRATCHES, AND CREASES EXIST
 IN FRAMES 1332 AND 1333. THESE WERE CAUSED BY THE TITLER. A
 WAVY PLUS DENSITY STREAK IS PRESENT WITHIN THE 1.0" NEAREST THE
 OUTBOARD EDGE IN FRAME 1424 TO 1451. A HEAT SPLICE OCCURS IN
 FRAME 1060 AND A MANUFACTURING SPLICE WITH ASSOCIATED LIGHT LEAKS

| COPIES RECEIVED 7 | | | |
|-------------------|-------------|------|-------|
| CyNo. | Office | Act. | Rec'd |
| 1 | Master File | | |
| 2 | OS | | |
| SAME | ADMIN | | |
| | SEC BR | | |
| | P&DS | | |
| | CSD | | |
| | IPD | | |
| | PD | | |
| 4 | PSD | | |
| 3 | TID | | |
| | PAG | | |
| | CIA/PID | | |
| | DIAXX-4 | | |
| | SPAD | | |
| | NSA LO | | |
| | DIAAP | | |
| | | | |
| | Destroyed | | |

SECRET

-2-

IS PRESENT IN FRAME 1195.

C. 9L SIDE: EDGE FOG AND ROLLER CHATTER ARE PRESENT ALONG THE INBOARD EDGE OF THE FIRST 75 PERCENT OF THE MISSION. OUTBOARD EDGE FOG IS CONTINUOUS THROUGHOUT THE MISSION. DUE TO PROBLEMS ENCOUNTERED DURING PROCESSING THE FILM WAS TORN AT FRAME 64. AN EMERGENCY CUT WAS MADE AND THE TEAR WAS REPAIRED WITH TAPE. BEGINNING AT THE SPLICE ON FRAME 64 THERE IS A PLUS DENSITY STREAK 0.25" FROM AND PARALLEL TO THE INBOARD EDGE. THE STREAK ENDS AT A HEAT SPLICE ON FRAME 1016. THERE ARE OTHER RANDOM LONGITUDINAL PLUS DENSITY STREAKS INTERMITTENTLY THROUGHOUT THE MISSION. ON FRAMES 831 TO 840 THERE ARE SEVERAL EMULSION LIFTS. AT THE DATA CHAMBER END OF EACH FRAME APPROXIMATELY HALF WAY BETWEEN THE FILM EDGES THERE IS A MINUS DENSITY STREAK WHICH APPEARS TO BE AN OBSTRUCTION CAUSED BY FOREIGN MATTER ADHERING TO THE FORMAT FRAME.

D. BOTH SIDES: THE LAST TITLED FRAME ON EACH SIDE IS 2181.

E. THERE WERE NO APPARENT CAMERA MALFUNCTIONS.

3. POSITIVE:

A. PRINTING AND PROCESSING WERE GOOD.

B. PI SUITABILITY IS GOOD.

C. CLOUDS COVER LESS THAN 1 PERCENT OF THIS MISSION.

S E C R E T

--END OF MESSAGE--